



## Single Survey Report

on

## 4 Meadow Crescent Kirkwall

**Customer:** Mr Kevin Groundwater

**Customer address:** 4 Meadow Crescent,  
Kirkwall

**Date of inspection:** 16<sup>th</sup> June, 2016

**Prepared by:** N J Coward, MRICS  
The Mart  
Hatston  
Kirkwall  
KW15 1FL

## 1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without the need to move any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right are taken facing the front of the property.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. were not inspected or reported on.

<b>Description</b>	2 storey semi-detached house, attached via garages.
<b>Accommodation</b>	Entrance Lobby, Hall, Sitting-room, Kitchen/Diner and WC on Ground Floor; Landing, 3 Bedrooms and Bathroom on the First Floor.
<b>Gross internal floor area (m<sup>2</sup>)</b>	127
<b>Neighbourhood and location</b>	The dwelling is part of a private residential area lying on the eastern side of Kirkwall.
<b>Age</b>	Approximately 5 years old
<b>Weather</b>	Overcast and rain.

## **Chimney stacks**

None present.

*Visually inspected with the aid of binoculars where appropriate*

## **Roofing including roof space**

Pitched roof clad in interlocking concrete tiles.

*Sloping roofs were visually inspected with the aid of binoculars where appropriate.*

*Where flat roofs exist they were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3 metre ladder externally.*

*Roof spaces were visually inspected and were entered where there was safe and reasonable access from a 3 metre ladder within the property.*

*Fixed access hatches will not be opened*

## **Rainwater fittings**

White plastic gutters and downpipes have been fitted.

*Visually inspected with the aid of binoculars where appropriate.*

## **Main walls**

Internal walls are SIP's (Structural Insulated Panels) with concrete block external walls, plastered and dashed.

*Visually inspected with the aid of binoculars.*

*Foundations and concealed parts were not exposed or inspected.*

<b>Windows, external doors and joinery</b>	<p>Double glazed NorDan windows, patio door and front entrance door. P.V.C. fasciaboards and soffits.</p> <p><i>Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open</i></p>
<b>External decorations</b>	<p>None present. <i>Visually inspected</i></p>
<b>Conservatories / porches</b>	<p>None present. <i>Visually inspected from ground level.</i></p>
<b>Communal areas</b>	<p>None present. <i>Circulation areas visually inspected where appropriate.</i></p>
<b>Garages and permanent outbuildings</b>	<p>Integral garage, semi-detached with neighbouring property. Concrete block walls, plastered and dashed beneath pitched roof clad with interlocking concrete tiles. Electric up and over garage door. <i>Visually inspected where appropriate.</i></p>
<b>Outside areas and boundaries</b>	<p>A lawn lies to both the front and rear of the dwelling. The site is bounded by concrete block walls and timber fences. <i>Visually inspected where appropriate.</i></p>
<b>Ceilings</b>	<p>Generally plasterboard sheeting, taped and filled. <i>Visually inspected from floor level.</i></p>

## **Internal walls**

Stud partitions clad in plasterboard, taped and filled.

*Visually inspected from floor level.*

*Using a moisture meter, walls were randomly tested for dampness where considered appropriate.*

## **Floors including sub floors**

Solid floor throughout the Ground Floor.

*Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.*

*Whenever possible, access is taken to sub-floor areas having a minimum clearance of 1 metre between underside of floor joists and solum as determined from the access hatch.*

*Otherwise, sub-floor areas were inspected only to the extent visible from a readily accessible hatch by way of an inverted head and shoulders inspection at the access point.*

*Fixed access hatches will not be opened.*

## **Internal joinery and kitchen fittings**

Modern units are fitted in the kitchen and Utility Area. Softwood skirtings and facings have been fitted throughout.

*Built-in cupboards were looked into but no stored items were moved.*

*Kitchen units were visually inspected excluding appliances.*

## **Chimney breasts and fireplaces**

None present.

*Visually inspected where appropriate. No testing of the flues or fittings was carried out.*

## **Internal decorations**

All walls and ceilings have been emulsioned and/or papered. Skirtings and facings have been both varnished.

## **Cellars**

None present.

*Visually inspected where appropriate.*

<b>Electricity</b>	Mains electricity wired in double insulated cable. Meter in a cupboard in Entrance Hall.
<b>Gas</b>	None present.
<b>Water, plumbing and bathroom fittings</b>	<p>Supply direct from Mains with limited internal storage. Modern units fitted in all bathrooms. Supply direct from Mains with limited internal storage. Modern units fitted in all bathrooms.</p> <p><i>Visual inspection of the accessible pipe work, water tanks, cylinders and fittings without removing any insulation.</i></p> <p><i>No tests whatsoever were carried out to the system or appliances.</i></p>
<b>Heating and hot water</b>	<p>Original installed heating system, NIBE Fighter 360P exhaust air heat pump to underfloor and radiators. As per the installer, this heating system has been disconnected and a Panasonic air to air heating system installed. Insulated hot water cylinder with an immersion heater.</p> <p><i>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.</i></p> <p><i>No tests whatsoever were carried out to the system or appliances.</i></p>
<b>Drainage</b>	<p>Public drainage system serves the dwelling.</p> <p><i>Drainage covers etc were not lifted.</i></p> <p><i>Neither drains nor drainage systems were tested.</i></p>
<b>Fire, smoke and burglar alarms</b>	<p>Smoke alarms are fitted throughout.</p> <p><i>Visually inspected where appropriate</i></p>

### **Any additional limits to inspection:**


None present.

An inspection for Japanese Knotweed or other invasive plant species was not carried out and unless otherwise stated, for the purposes of this report, it is assumed that there is no Japanese Knotweed or other invasive plant species within the boundaries of the property or in neighbouring properties.

There was no access for inspection to the foundations, to the underside of timber floors or to behind wall linings. The drainage system was not open to inspection.

Orkney has a high incidence of naturally occurring Radon gas. No investigation has been carried out to test for the presence of the gas in the dwelling.







## Sectional diagram showing elements of a typical house





## 2 CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of three categories.

	<b>Structural movement</b>
Repair category:	1
Notes:	No evidence of current movement was noted.
	<b>Dampness, rot and infestation</b>
Repair category:	1
Notes:	No dampness, rot or infestation was noted.
	<b>Chimney stacks</b>
Repair category:	N/A
Notes:	
	<b>Roofing including roof space</b>
Repair category:	1
Notes:	No defects were noted.
	<b>Rainwater fittings</b>
Repair category:	1
Notes:	No defects were noted. Weather conditions at the time of the inspection prevent comment on the efficacy of the system.
	<b>Main walls</b>
Repair category:	1
Notes:	No defects were noted.



### Windows, external doors and joinery

Repair category:

1

Notes:

No defects were noted.



### External decorations

Repair category:

N/A

Notes:



### Conservatories / porches

Repair category:

N/A

Notes:



### Communal areas

Repair category:

N/A

Notes:



### Garages and permanent outbuildings

Repair category:

1

Notes:

No defects were noted.



### Outside areas and boundaries

Repair category:

1

Notes:

No defects were noted.



### Ceilings

Repair category:

1

Notes:

No defects were noted.



### Internal walls

Repair category: 1

Notes: No defects were noted.



### Floors including sub-floors

Repair category: 1

Notes: All are firm and level and without significant defect. Fitted floor coverings prevented close examination. No access to sub-floor void.



### Internal joinery and kitchen fittings

Repair category: 1

Notes: All joinery is in sound condition.



### Chimney breasts and fireplaces

Repair category: N/A

Notes:



### Internal decorations

Repair category: 1

Notes: No defects were noted.



### Cellars

Repair category: N/A

Notes:



## Electricity

Repair category:

1

Notes:

No defects were noted. It is recommended that as the installation is more than 5 years old it be checked by an electrical engineer and his recommendations be implemented.



## Gas

Repair category:

N/A

Notes:



## Water, plumbing and bathroom fittings

Repair category:

1

Notes:

No defects were noted.



## Heating and hot water

Repair category:

1

Notes:

It is understood that the system is operating correctly as the dwelling was warm during inspection. It is recommended that it be checked by a suitably qualified Heating Engineer and his recommendations be implemented.



## Drainage

Repair category:

1

Notes:

The system is operating correctly.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

<b>Structural movement</b>	<b>1</b>	<p><b>Repair Categories</b></p> <p><b>Category 3:</b> Urgent Repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.</p> <p><b>Category 2:</b> Repairs or replacement requiring future attention, but estimates are still advised.</p> <p><b>Category 1:</b> No immediate action or repair is needed.</p>
<b>Dampness, rot and infestation</b>	<b>1</b>	
<b>Chimney stacks</b>	<b>N/A</b>	
<b>Roofing including roof space</b>	<b>1</b>	
<b>Rainwater fittings</b>	<b>1</b>	
<b>Main walls</b>	<b>1</b>	
<b>Windows, external doors and joinery</b>	<b>1</b>	
<b>External decorations</b>	<b>N/A</b>	
<b>Conservatories / porches</b>	<b>N/A</b>	
<b>Communal areas</b>	<b>N/A</b>	
<b>Garages and permanent outbuildings</b>	<b>1</b>	
<b>Outside areas and boundaries</b>	<b>1</b>	
<b>Ceilings</b>	<b>1</b>	
<b>Internal walls</b>	<b>1</b>	
<b>Floors including sub-floors</b>	<b>1</b>	
<b>Internal joinery and kitchen fittings</b>	<b>1</b>	
<b>Chimney breasts and fireplaces</b>	<b>N/A</b>	
<b>Internal decorations</b>	<b>1</b>	
<b>Cellars</b>	<b>N/A</b>	
<b>Electricity</b>	<b>1</b>	
<b>Gas</b>	<b>N/A</b>	
<b>Water, plumbing and bathroom fittings</b>	<b>1</b>	
<b>Heating and hot water</b>	<b>1</b>	
<b>Drainage</b>	<b>1</b>	

## Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

## Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

### **3. ACCESSIBILITY INFORMATION**

#### Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes: Parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

<b>1. Which floor(s) is the living accommodation on?</b>	<b>Ground Floor</b>
<b>2. Are there three steps or fewer to a main entrance door of the property?</b>	<b>Yes</b>
<b>3. Is there a lift to the main entrance door of the property?</b>	<b>No</b>
<b>4. Are all door openings greater than 750mm?</b>	<b>Yes</b>
<b>5. Is there a toilet on the same level as the living room and kitchen?</b>	<b>Yes</b>
<b>6. Is there a toilet on the same level as a bedroom?</b>	<b>Yes</b>
<b>7. Are all rooms on the same level with no internal steps or stairs?</b>	<b>No</b>
<b>8. Is there unrestricted parking within 25 metres of an entrance door to the building?</b>	<b>Yes</b>



#### 4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

##### **Matters for a solicitor or licensed conveyancer**

None

##### **Estimated re-instatement cost for insurance purposes**

**£210000**

##### **Valuation and market comments**

I am of the opinion that the open market value of 4 Meadow Crescent Kirkwall, as inspected, is fairly stated at £175000

**Report author:** N J Coward

**Address:** The Mart  
Hatston  
Kirkwall  
KW15 1FL

**Signed:**

**Date of report:**  Monday, 20 June 2016



### Terms and Conditions

#### PART 1 - GENERAL

##### 1.1 The Surveyor

The Seller has engaged the Surveyor to provide the Single Survey Report. The Seller has also engaged the Surveyor to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyor is authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyor, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyor during the conveyancing process which materially affects the valuation stated in the Report, the Surveyor reserves the right to reconsider the valuation. Where the Surveyor requires to amend the valuation in consequence of such information, they will issue an amended Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report is transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.<sup>1</sup>

If the Surveyor has had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyor has a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

<sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

## **1.2 The Report**

The Surveyor will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice. The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyor.

## **1.3 Liability**

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and

- the professional advisers of any of these.

The Surveyor acknowledges that his duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyor accepts no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyor accepts no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### **1.4 Generic Mortgage Valuation Report**

The Surveyor undertakes to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### **1.5 Transcript Mortgage Valuation For Lending Purposes**

The Surveyor undertakes that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report<sup>2</sup>.

#### **1.6 Intellectual Property**

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyor and shall remain his exclusive property unless they assign the same to any other party in writing.

#### **1.7 Payment**

The Surveyor is entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid.

Additional fees will be charged for subsequent inspections and Reports

---

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

## 1.8 Cancellation

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion. In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

## 1.9 Precedence

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

## 1.10 Definitions

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is *The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length*

*transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion*

- the “Property” is the property which forms the subject of the Report;
- the “Purchaser” is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the “Report” is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the “Seller” is/are the proprietor(s) of the Property;
- the “Surveyor” is the author of the Report on the Property; and the firm whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

## **PART 2 – DESCRIPTION OF THE REPORT**

### **2.1 The Service**

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company.

### **2.2 The Inspection**

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller’s permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

### 2.3 The Report

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

1. Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
3. Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

### 2.4 Services

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

## 2.5 Accessibility

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

## 2.6 Energy Report

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

## 2.7 Valuation and Conveyancer Issues

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

*“Market Value” is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion .* In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

*“Re-instatement cost” is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).*

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property